

MATTITUCK

SOILS - DRAINAGE CLASS


Map Symbols

- Major Surface Watershed Divide
- Long Island Sound Study Boundary

Soils

Drainage Class

- Null
- Excessively Drained
- Well Drained
- Moderately Well Drained
- Somewhat Poorly Drained
- Poorly Drained
- Very Poorly Drained



Long
Island Sound

